

Cofe

PATENT

### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of: Examiner: J. Whipkey YUICHI HOSODA, et al. Group Art Unit: 2612 Appl. No.: 09/910,896 Filed: July 24, 2001 For: IMAGE RECORDING DEVICE, IMAGE INPUT DEVICE, AND DATA PROCESSOR, IMAGE RECORDING METHOD, AND STORAGE MEDIUM RECORDING IMAGE RECORD CONTROL PROGRAM U.S. Patent No.: 6,965,404 B2 August 2, 2006 Issued: November 15, 2005 Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

> REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

| 68/04/2006 JADD01 | 6965404 |
| 61 FC:1811 | 100.00 OP

Patentees' undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Frank L. Cire

Attorney for Patentees Registration No.: 42,419

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

CA\_MAIN 117572v1

# CERTIFICATE OF CORRECTION

PATENT NO.

6,965,404 B2

DATED

November 15, 2005

INVENTOR(S) :

Hosoda et al.

Page 1 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## **COVER PAGE**:

- (75) Inventors: "Nobuyodhi Kakigi" should read -- Nobuyoshi Kakigi --.
- (56) References Cited, FOREIGN PATENT DOCUMENTS:

"62244870 A" should read -- 62-244870 A --;

"07187491 A" should read -- 07-187491 A --:

"09086783 A" should read -- 09-086783 A --;

"10013609 A" should read -- 10-013609A --; and

"11069076 A" should read --11-069076 A --.

## DRAWINGS:

Sheet 6, FIG. 6, "PORT DESIGNATED" should read -- PORT BEEN DESIGNATED --;

Sheet 8, FIG. 8, "WRINING" should read -- WARNING --;

Sheet 15, FIG. 15, "ABNORMALLY" should read -- ABNORMALITY --;

Sheet 21, FIG. 21, "CASSETTE1" should read -- CASSETTE 1 --;

Sheet 28, FIG. 29, "ORT" should read -- PORT --;

Sheet 33, FIG. 34 (2 occurrences), "INSUTRUCTION" should read -- INSTRUCTION --,

"DEGITAL" should read -- DIGITAL --, and "WRINING" should read

-- WARNING --;

Sheet 46, FIG. 47, "INSUTRUCTION" should read -- INSTRUCTION --;

Sheet 50, FIG. 51, "HOTOGRAPH" should read -- PHOTOGRAPH --; and

Sheet 53, FIG. 54, "POST" should read -- HOST --.

#### COLUMN 5:

Line 34, "a laborious" should -- laborious --.

#### COLUMN 7:

Line 18, "detained" should read -- detailed --.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. 6,965,404 B2

No. of add'l. copies @ 30¢ per page

# **CERTIFICATE OF CORRECTION**

PATENT NO.

6,965,404 B2

DATED

November 15, 2005

INVENTOR(S) :

Hosoda et al.

Page 2 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 11:

Line 15, "collect" should read -- collects --; and Line 47, "clerks" should read -- clerk --.

#### COLUMN 19:

Line 28, "roller 205" should read -- rollers 205 ---.

## COLUMN 20:

Line 21, "genera-purpose" should read -- general-purpose --.

## COLUMN 21:

Line 9, "boy" should read -- body --;

Line 31, "flatter 280" should read -- flapper 280 --;

Line 36, "flatter 280" should read -- flapper 280 --; and

Line 67, "staple" should read -- stapler --.

#### COLUMN 22:

Line 15, "roller 205" should read -- rollers 205 --;

Line 17, "downsream" should read -- downstream --;

Line 28, "flatter 211" should read -- flapper 211 --; and

Line 64, "printing" should read -- printing, --.

#### COLUMN 23:

Line 43, "in to" should read -- into --.

## COLUMN 25:

Line 2, "he" should read -- the --; and

Line 49, "troubles" should read -- troubles, --.

#### **MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. <u>6,965,404 B2</u>

No. of add'l. copies @ 30¢ per page

 $\Rightarrow$  \_\_\_

## UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

6,965,404 B2

DATED

November 15, 2005

INVENTOR(S) :

Hosoda et al.

Page 3 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 26:

Line 63, "gape" should read -- gap --.

#### COLUMN 28:

Line 22, "bases" should read -- basis --;

Line 30, "bases." should read -- basis. --;

Line 33, "on a" should read -- on --;

Line 34, "bases," should read -- basis, --; and

Line 47, "the all" should read -- all the --.

## COLUMN 29:

Line 5, "temporally" should read -- temporarily --; and

Line 56, "processings." should read -- processing. --.

## COLUMN 31:

Lines 6 and 55, "bases" should read -- basis --.

## COLUMN 32:

Lines 18 and 61, "bases" should read -- basis --.

#### COLUMN 33:

Line 5, "sheet" should read -- sheet, --;

Line 7, "person" should read -- persons --;

Line 37, "hardball" should read -- "handball --; and

Line 65, "operation" should read -- operation by --.

## COLUMN 34:

Line 13, "hardball" should read -- "handball --; and

Line 61, "of an" should read -- of a --.

## MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. 6,965,404 B2

No. of add'l. copies @ 30¢ per page

 $\Box$ 

## UNITED STATES PATENT AND TRADEMARK OFFICE

# CERTIFICATE OF CORRECTION

PATENT NO.

6,965,404 B2

DATED

November 15, 2005

INVENTOR(S) :

Hosoda et al.

Page 4 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 35:

Line 49, "having" should read -- having been --.

## COLUMN 37:

Line 37, "trays 215" should read -- trays 251 ---.

#### COLUMN 38:

Line 58, "hose 51" should read -- host 51 --.

## COLUMN 39:

Line 62, "(907)." should read -- (S907). --.

## COLUMN 41:

Lines 10 and 56, "hardball" should read -- "handball --.

## COLUMN 43:

Lines 10 and 20, "information" should read -- information, --;

Line 34, "camera" should read -- camera, --;

Line 56, "hardball" should read -- "handball --; and

Line 60, "temporally" should read -- temporarily --.

## COLUMN 47:

Lines 18 and 51, "bases" should read -- basis --; and

Line 46, "copies," should read -- copies," --.

#### COLUMN 48:

Line 1, "become" should read -- becomes --;

Line 17, "print" should read -- print, --;

Line 22, "password" should read -- password, --; and

Line 37, "operation" should read -- operation, --.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. <u>6,965,404 B2</u>

No. of add'l. copies @ 30¢ per page

AUG US ZUO6

# **CERTIFICATE OF CORRECTION**

PATENT NO.

6,965,404 B2

DATED

November 15, 2005

INVENTOR(S) :

Hosoda et al.

Page 5 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 49:

Line 33, "address" should read -- address, --; and

Line 56, "the" should be deleted.

## COLUMN 50:

Line 4, "bases" should read -- basis --;

Line 42, "printer 102" should read -- printer 102, --;

Line 53, "office" should read -- office, --; and

Line 62, "operation" should read -- operation, --.

## COLUMN 51:

Line 35, "address" should read -- address, --;

Line 36, "operations" should read -- operations, --; and

Line 37, "password" should read -- password, --.

## COLUMN 52:

Line 55, "form" should read -- from --; and

Line 56, "terminal" should read -- terminal, --.

#### COLUMN 53:

Line 25, "settings" should read -- settings, --;

Lines 26, 28, 32, and 47, "browser" should read -- browser, --; and

Line 66, "setting" should read -- setting, --.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30)

## PATENT NO. 6,965,404 B2

No. of add'l. copies @ 30¢ per page

## UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

6,965,404 B2

DATED

November 15, 2005

INVENTOR(S) :

Hosoda et al.

Page 6 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### COLUMN 54:

Line 2, "printing" should read -- printing, --;

Line 16, "indication" should read -- indication, --;

Line 19, "control" should read -- control, -- and "setting" should read -- setting, --;

Line 23, "service" should read -- service, --;

Line 30, "card" should read -- card, --;

Line 54, "account" should read -- account, --; and

Line 60, "ID" should read -- ID, --.

## COLUMN 55:

Line 1, "host" should read -- host, --;

Line 24, "printer" should read -- printer, --;

Line 26, "device" should read -- device, --;

Lines 38 and 40, "that" should read -- those --;

Line 41, "table" should read -- table, --;

Line 44, "ROM" should read -- ROM, --;

Line 50, "system)" should read -- system), --;

Line 55, "camera" should read -- camera, --;

Line 56, "card" should read -- card, --;

Line 58, "an" should be deleted; and

Line 59, "device" should read -- device, --.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. 6,965,404 B2

No. of add'l. copies @ 30¢ per page

 $\Rightarrow$  \_\_\_

# Staple Here Only! Staple Here

## UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

6,965,404 B2

DATED

November 15, 2005

INVENTOR(S) :

Hosoda et al.

Page 7 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 56:

Line 3, "charges" should read -- charges, --;

Line 5, "printer" should read -- printer, --;

Lines 6 and 26, "camera" should read -- camera, --;

Line 7, "printing" should read -- printing, --;

Line 13, "shop" should read -- shop, --;

Line 14, "delivery" should read -- delivery, --;

Line 21, "images" should read -- images, --; and

Line 29, "device" should read --device, --.

CA\_MAIN 115902v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. 6,965,404 B2

No. of add'l. copies @ 30¢ per page

 $\Rightarrow$ 

# CERTIFICATE OF CORRECTION

PATENT NO. :

6,965,404 B2

DATED

November 15, 2005

INVENTOR(S) :

Hosoda et al.

Page 1 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## **COVER PAGE:**

- (75) Inventors: "Nobuyodhi Kakigi" should read -- Nobuyoshi Kakigi --.
- (56) References Cited, FOREIGN PATENT DOCUMENTS:

"62244870 A" should read -- 62-244870 A --;

"07187491 A" should read -- 07-187491 A --;

"09086783 A" should read -- 09-086783 A --;

"10013609 A" should read -- 10-013609A --; and

"11069076 A" should read --11-069076 A --.

## DRAWINGS:

Sheet 6, FIG. 6, "PORT DESIGNATED" should read -- PORT BEEN DESIGNATED --;

Sheet 8, FIG. 8, "WRINING" should read -- WARNING --;

Sheet 15, FIG. 15, "ABNORMALLY" should read -- ABNORMALITY --;

Sheet 21, FIG. 21, "CASSETTE1" should read -- CASSETTE 1 --;

Sheet 28, FIG. 29, "ORT" should read -- PORT --;

Sheet 33, FIG. 34 (2 occurrences), "INSUTRUCTION" should read -- INSTRUCTION --,

"DEGITAL" should read -- DIGITAL --, and "WRINING" should read

-- WARNING --;

Sheet 46, FIG. 47, "INSUTRUCTION" should read -- INSTRUCTION --;

Sheet 50, FIG. 51, "HOTOGRAPH" should read -- PHOTOGRAPH --; and

Sheet 53, FIG. 54, "POST" should read -- HOST --.

#### COLUMN 5:

Line 34, "a laborious" should -- laborious --.

#### COLUMN 7:

Line 18, "detained" should read -- detailed --.

#### **MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. 6,965,404 B2

No. of add'l. copies @ 30¢ per page

 $\Rightarrow$  \_\_\_\_

# **CERTIFICATE OF CORRECTION**

PATENT NO.

6,965,404 B2

DATED

November 15, 2005

INVENTOR(S) :

Hosoda et al.

Page 2 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 11:

Line 15, "collect" should read -- collects --; and

Line 47, "clerks" should read -- clerk --.

## COLUMN 19:

Line 28, "roller 205" should read -- rollers 205 ---.

#### COLUMN 20:

Line 21, "genera-purpose" should read -- general-purpose --.

## COLUMN 21:

Line 9, "boy" should read -- body --;

Line 31, "flatter 280" should read -- flapper 280 --;

Line 36, "flatter 280" should read -- flapper 280 --; and

Line 67, "staple" should read -- stapler --.

#### COLUMN 22:

Line 15, "roller 205" should read -- rollers 205 --;

Line 17, "downsream" should read -- downstream --;

Line 28, "flatter 211" should read -- flapper 211 --; and

Line 64, "printing" should read -- printing, --.

#### COLUMN 23:

Line 43, "in to" should read -- into --.

#### COLUMN 25:

Line 2, "he" should read -- the --; and

Line 49, "troubles" should read -- troubles, --.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. <u>6,965,404 B2</u>

No. of add'l. copies @ 30¢ per page

## UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

6,965,404 B2

DATED

November 15, 2005

INVENTOR(S) :

Hosoda et al.

Page 3 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 26:

Line 63, "gape" should read -- gap --.

#### COLUMN 28:

Line 22, "bases" should read -- basis --;

Line 30, "bases." should read -- basis. --;

Line 33, "on a" should read -- on --;

Line 34, "bases," should read -- basis, --; and

Line 47, "the all" should read -- all the --.

## COLUMN 29:

Line 5, "temporally" should read -- temporarily --; and

Line 56, "processings." should read -- processing. --.

## COLUMN 31:

Lines 6 and 55, "bases" should read -- basis --.

#### COLUMN 32:

Lines 18 and 61, "bases" should read -- basis --.

#### COLUMN 33:

Line 5, "sheet" should read -- sheet, --;

Line 7, "person" should read -- persons --;

Line 37, "hardball" should read -- "handball --; and

Line 65, "operation" should read -- operation by --.

#### COLUMN 34:

Line 13, "hardball" should read -- "handball --; and

Line 61, "of an" should read -- of a --.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. 6,965,404 B2

No. of add'l. copies @ 30¢ per page

=>

## UNITED STATES PATENT AND TRADEMARK OFFICE

# CERTIFICATE OF CORRECTION

PATENT NO.

6,965,404 B2

DATED

November 15, 2005

INVENTOR(S) :

Hosoda et al.

Page 4 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 35:

Line 49, "having" should read -- having been --.

#### COLUMN 37:

Line 37, "trays 215" should read -- trays 251 --.

## COLUMN 38:

Line 58, "hose 51" should read -- host 51 --.

## <u>COLUMN 39</u>:

Line 62, "(907)." should read -- (S907). --.

## COLUMN 41:

Lines 10 and 56, "hardball" should read -- "handball --.

#### COLUMN 43:

Lines 10 and 20, "information" should read -- information, --;

Line 34, "camera" should read -- camera, --;

Line 56, "hardball" should read -- "handball --; and

Line 60, "temporally" should read -- temporarily --.

## COLUMN 47:

Lines 18 and 51, "bases" should read -- basis --; and

Line 46, "copies," should read -- copies," --.

## COLUMN 48:

Line 1, "become" should read -- becomes --;

Line 17, "print" should read -- print, --;

Line 22, "password" should read -- password, --; and

Line 37, "operation" should read -- operation, --.

## MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. 6,965,404 B2

No. of add'l. copies @ 30¢ per page

 $\Rightarrow$  —

AUG 0 0 2006

## CERTIFICATE OF CORRECTION

PATENT NO.

6,965,404 B2

DATED

November 15, 2005

INVENTOR(S) :

Hosoda et al.

Page 5 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 49:

Line 33, "address" should read -- address, --; and

Line 56, "the" should be deleted.

## COLUMN 50:

Line 4, "bases" should read -- basis --;

Line 42, "printer 102" should read -- printer 102, --;

Line 53, "office" should read -- office, --; and

Line 62, "operation" should read -- operation, --.

## COLUMN 51:

Line 35, "address" should read -- address, --;

Line 36, "operations" should read -- operations, --; and

Line 37, "password" should read -- password, --.

#### COLUMN 52:

Line 55, "form" should read -- from --; and

Line 56, "terminal" should read -- terminal, --.

## COLUMN 53:

Line 25, "settings" should read -- settings, --;

Lines 26, 28, 32, and 47, "browser" should read -- browser, --; and

Line 66, "setting" should read -- setting, --.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. 6,965,404 B2

No. of add'l. copies @ 30¢ per page

⇨.

# **CERTIFICATE OF CORRECTION**

PATENT NO.

6,965,404 B2

**DATED** 

November 15, 2005

INVENTOR(S) :

Hosoda et al.

Page 6 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 54:

Line 2, "printing" should read -- printing, --;

Line 16, "indication" should read -- indication, --;

Line 19, "control" should read -- control, -- and "setting" should read -- setting, --;

Line 23, "service" should read -- service, --:

Line 30, "card" should read -- card, --;

Line 54, "account" should read -- account, --; and

Line 60, "ID" should read -- ID, --.

## COLUMN 55:

Line 1, "host" should read -- host, --;

Line 24, "printer" should read -- printer, --;

Line 26, "device" should read -- device, --;

Lines 38 and 40, "that" should read -- those --;

Line 41, "table" should read -- table, --;

Line 44, "ROM" should read -- ROM, --;

Line 50, "system)" should read -- system), --;

Line 55, "camera" should read -- camera, --;

Line 56, "card" should read -- card, --;

Line 58, "an" should be deleted; and

Line 59, "device" should read -- device, --.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30)

PATENT NO. 6,965,404 B2

No. of add'i. copies @ 30¢ per page

# Stable Only! PRINTER'S TRIM LINE

## UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

6,965,404 B2

DATED

November 15, 2005

INVENTOR(S) :

Hosoda et al.

Page 7 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 56:

Line 3, "charges" should read -- charges, --;

Line 5, "printer" should read -- printer, --;

Lines 6 and 26, "camera" should read -- camera, --;

Line 7, "printing" should read -- printing, --;

Line 13, "shop" should read -- shop, --;

Line 14, "delivery" should read -- delivery, --;

Line 21, "images" should read -- images, --; and

Line 29, "device" should read --device, --.

CA\_MAIN 115902v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. 6,965,404 B2

No. of add'l. copies @ 30¢ per page

 $\Rightarrow$